Work Order ID 74972 *74972* Page 1 Thursday, October 13, 2011 2:38:05 PM Item ID: D3230-041 Accept *N900040100* Setup Start Revision ID: Item Name Basket Wedge Assembly Start Date: 10/13/2011 Start Otv: 1.00 **Cust Item ID: Required Date:** 10/14/2011 Rea'd Otv: 1.00 **Customer:** Reference: Start Run Process Plan: MK Date: |- |0-|3 Tooling: Approvals: Date: Stop Date: OC: SPC (Y/N): Date: Operation Sequence ID/ Set Up/ Tool ID Tool # Plan Reject Reject Accept Insp. Work Center ID Description Oty Otv Code Number Stamp **Run Hours** Draw Nbr **Revision Nbr** D3230 Rev C 110 0.00 Large Fab *110* Large Fab 0.00 Memo Large Fab 1-Cut 3/4 x 3/4 square tubing as per Dwg D3230 2- Drill and c'sink holes 3- cut mesh as per dwg

4 -Deburr & Remove all Markings From Material

5-Weld bushings and fabricate basket wedge assembly as per D3230

A/R SS ROD Batch: 117884

120 QC9- Inspect visual per QSI004- Fusion Welds 0.00

120 QC

0.00 Memo Quality Control

Dart Aerospace	Ltd
----------------	-----

W/O:	, copace and	WORK ORDER	WORK ORDER CHANGES										
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector						
				1		<u> </u>	<u></u>						

Part No: PAR #:	Fault Category:	NCR: Yes No DQA: Date:
Resolution:	Disposition:	QA: N/C Closed: Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCH)													
	T	D		Corrective Action Section B	Sign &	Verification	Approval	Approval							
DATE	STEP	Description of NC Section A	Initial Action Description Chief Eng Chief Eng			Section C	Chief Eng	QC Inspector							
							. •	M3 ()*							
								1							
						i.	<i>s</i> .:								
	-														
		·													
		· · · · · · · · · · · · · · · · · · ·						1							

•													
Work Orde Thursday, Octob				*74972*								Page 2	?
Item ID: Revision ID: Item Name:	D3230-041 Basket Wedge	Assembly		Accept	*N900	040	100)*	Setup	Start Stop		S1* S2*	=
Start Date: 10/13/2011 Start Qty: 1.00 Required Date: 10/14/2011 Req'd Qty: 1.00 Reference:			*1* *1*	0 100 100 110 12 0						1,4,			
Approvals: Process Plan: QC:		n:	Date:	Tooling: SPC (Y/N):		ate:			Run	Start Stop		R1* R2*	
Sequence ID/ Work Center I	D	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accep Qty	ot Re Qt		Reject Number	Insp. Stamp	_
*130 *130*		QC5- Inspect part compl	eteness to step on W/O	0.00	rolle			(a))				

140

White Gloss(Ref:4.3.5.1) per QSI005 4.3-Alum

0.00

140 Powdercoat

Quality Control

Powder Coating

Memo

Memo

1ST COAT: START TIME: OVEN TEMPERATURE: FINISH TIME:

**** if necessary*****

2ND COAT: START TIME:

OVEN TEMPERATURE: FINISH TIME:

	ospace		W	RK ORDER CHANGES				
W/O: DATE	STEP	PRO	CEDURE CHA	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
	·							
	·							
Part No	o:	PAR #:	Fault Cate	egory: N	CR: Yes	No DQA:	Date: _	
	R	esolution:	Dispositi	on:	A: N/C Clo	sed:	Date: _	
NCR:			WORK ORD	ER NON-CONFORMANC	CE (NCR)		
		Description of NC		Corrective Action Section B		Verification		
DATE	STEP	Description of NC Section A Init Chief		Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspecto

STEP	Description of NC Section A	Initial Chief Eng	Action Elescription Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
						. ~	,·
						, `	
	STEP	STEP Description of NC Section A	STEP Description of NC Section A Initial Chief Eng	STEP Description of NC Section A Initial Chief Eng Chief Eng Chief Eng	STEP Description of NC Section A Initial Chief Eng Chief	STEP Description of NC Section A Initial Chief Eng Action Description Chief Eng Section C	Ciller Elig

ds

Work Order 1D /49/2 Thursday, October 13, 2011 2:38:05 PM				*74972*							Pag			
Item ID: Revision ID: Item Name:	D3230-041 Basket Wedge	e Assembly		Accept	*N900	040	100	↑* Setup Star Sto			14771			
Start Date: Required Date: Reference:	10/13/2011 10/14/2011	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item II Customer:	D:					14.	12		
Approvals:	Process Pla	an:	Date:	Tooling: SPC (Y/N):		ite:			Run	Start Stop	*NF	₹1* ₹2*		
Sequence ID/ Work Center II 150 *150* QC Quality Control 180 *180* Packaging Packaging	D	Operation Description QC3- Inspect Part Finish Memo Identify as per dwg & Sto Packaging Memo	ck Location:	Set Up/ Run Hours 0.00 0.00	Tool ID	Tool#	Plan Code	Accept Qty	Qty		Reject Number	Insp. Stamp		
*190 *190* QC Quality Control		QC21- Final Inspection - Memo	Work Order Release	0.00							1100 M	18 D F 10 18		

	rospace	, =		WORK ORDER	CHANGES					
W/O: DATE	STEP		PR	OCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	1				·		11. F			
· ·				•			,			
Part No	o:		PAR #:	Fault Category:	NCR	: Yes	No DQ	A:	Date: _	
				Disposition:						
NCR:				WORK ORDER NON-COM					e.	
	1			Corrective Action	on Section B		Vorifie	cation	Annroval	Approval

	WORK ORDER NON-CONFORMANCE (NCh)													
T	Description of NO		Corrective Action Section B		Verification	Approval	Approval							
STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector							
						·								
	STEP	Description of NC	STEP Description of NC	STEP Description of NC Section A Initial Action Description	STEP Description of NC Corrective Action Section B Initial Action Description Sign &	STEP Description of NC Corrective Action Section B Verification Section C	STEP Description of NC Corrective Action Section B Verification Section C Se							

Picklist Print

Thursday, October 13, 2011 2:38:04 PM

Work Order ID:

74972

Parent Item:

D3230-041

Parent Item Name:

Basket Wedge Assembly

Start Date: 10/13/2011

Required Date: 10/14/2011

Page 1

Start Qty: 1.00

Required Qty: 1.00

Comments:	IPP Rev:D 09-02	-25 rev.c as per dv	vg DD	verified by:E0									
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Statu
D2232-3 Basket Hinge		Manufactured	No		-	110	Each	5.0000	2	2	120	1.10	. 1 =
Dasket Hinge				Location		Loc Qty	· Lo	oc Code	 			, , , ,	
				ST		5				-			
D2327-3			NI.	729)29	5	F 1	10 0000	- G	<u>ل</u> ــــــــــــــــــــــــــــــــــــ			
Spacer Bushing		Manufactured	No			110	Each	18.0000	2	26	£1/11	0.	17
				<u>Location</u>		Loc Qty	Lo	oc Code	٠	,		- 20,	
				WA .	/	18							-
				729	971	1 17			(5				
D3759-1		Manufactured	No	<u>-</u> ــــ		110	Each	87.0000	5	5 /	26/1		,
Bushing	•			Location		Loc Qty	La	oc Code			76 / /	<u> </u>	_/
				WA		85		oc Code	-				
				723	316	85			(5				
rans				WA005	1	2						1	
M304EX0.75-16F Expanded Metal Flat SS		Purchased	No	869	189	110	sf	779.7855	5.15	5.421052	26 /	. 4. ₁ 6	2./
	•			Location		Loc Qty	<u>L</u> c	oc Code			•		
				WA		779.78548							
					7197	102.9036	•						
					7896 8153	53.3264 82.2683							
					8153 8248	33.0983							
		-			3597	73.01888			KU	1210	, ,		

118955

119180

1.15.17 320

Dart	Aerospace	Ltd
-------------	------------------	-----

W/O:			WORK ORDER CHANGES							
DATE	STEP	 PRO	CEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
		 			*					
							,			
		,								
		 	<u> </u>				<u> </u>			
Part No	o:	PAR #:	Fault Category:	NCR: Ye	s No DO)A:	Date: _			
			Disposition:	QA: N/C	Closed: _		Date: _			

NCR:			WORK ORDER NON-CONFORMANCE (NCR)										
	1 - 1			Corrective Action Section B		Verification	Approval	Approval QC Inspector					
DATE	DATE STEP Description of Section A	Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng						
7						-	`						
							<u> </u>						
	1	1											

Picklist Print

Thursday, October 13, 2011 2:38:04 PM

Page 2

Work Order ID:

74972

Parent Item:

D3230-041

Parent Item Name:

Basket Wedge Assembly

M304TS0.750W.065

304 SQ Tube .75x.75x.065W

Purchased

No

Start Date: 10/13/2011

Required Date: 10/14/2011

Start Qty: 1.00

Required Qty: 1.00


Qty: 1.00 Requir

110 f 686.1922 **25.2966 26.628** C11.10.14

Location	Loc Qty	Loc Code	
MAT018	664.5280585		
117636	67.9987		
118773	596.529359		<u> 26.628</u>
WA	6.0667		
118181	6.0667		
WA007	15.5974906		
116267	14.628472		
116763	0.9690186		

W/O:			WORK ORI	DER CHAN	GES					
DATE	STEP	PROC	CEDURE CHANGE		В	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
										1
					·					
Dart No		PAR #:	Fault Category:		NCR:	Yes	No DC	A:	Date: _	
rait INC			Disposition:			vc c	losed: _		Date: _	


NCR:	R: WORK ORDER NON-CONFORMANCE (NCR)								
				Corrective Action Section B		Verification	Approval	Approval QC Inspector	
DATE	STEP	Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng		
								· ·	
			:						
					·			·	



Dart Ae	rospace L										
W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
						,					
					1						

Part No:	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
·	Resolution:	Disposition:	QA: N/C Closed	l:	Date:

NCR:			WORK ORI	DER NON-CONFORMANC	E (NCR)			
	†			Corrective Action Section B		Verification	Approval	Approval QC Inspector
DATE	STEP	Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	
	1							;
:								
								:
		-						
							Í	
				P			ļ	




Dart	Aero	space	e Ltd
------	------	-------	-------

	WORK ORDER CHANGES	WORK ORDER CHANGES							
STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
				\$ +.					
<u> </u>									
			. •						
	STEP		Dy.	Date Date	STEP PROCEDURE CHANGE By Date Qty	STEP PROCEDURE CHANGE By Date Qty Chief Eng / Prod Mgr			

Part No:	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
Posolution:		Disposition:	QA: N/C Closed	l:	Date:

NCR:		V	VORK ORE	DER NON-CONFORMANC	E (NCH)	r-		
:		Description of NC		Corrective Action Section B	T-0:	Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
		Øs.						
		131.						
							·	
		·						
: .					. • ^			
			*sain					
				·				



PACE 110 CANADA ANGERTALW ANGERTALW

TELL SE

